



## AISC Live Webinars

---

**Today's live webinar will begin shortly. Please stand by.**

Today's audio will be broadcast through the internet. Please be sure to turn up the volume on your speakers.

Please type any questions or comments in the Q&A window.



**Smarter.  
Stronger.  
SteelDay.**



## AISC Live Webinars

---

### AIA Credit

AISC is a Registered Provider with The American Institute of Architects Continuing Education Systems (AIA/CES). Credit(s) earned on completion of this program will be reported to AIA/CES for AIA members. Certificates of Completion for both AIA members and non-AIA members are available upon request.

This program is registered with AIA/CES for continuing professional education. As such, it does not include content that may be deemed or construed to be an approval or endorsement by the AIA of any material of construction or any method or manner of handling, using, distributing, or dealing in any material or product.

Questions related to specific materials, methods, and services will be addressed at the conclusion of this presentation.



Smarter.  
Stronger.  
SteelDay.

## AISC Live Webinars

---

### Copyright Materials

This presentation is protected by US and International Copyright laws. Reproduction, distribution, display and use of the presentation without written permission of AISC is prohibited.

© The American Institute of Steel Construction 2020

The information presented herein is based on recognized engineering principles and is for general information only. While it is believed to be accurate, this information should not be applied to any specific application without competent professional examination and verification by a licensed professional engineer. Anyone making use of this information assumes all liability arising from such use.



Smarter.  
Stronger.  
SteelDay.



## AISC Live Webinars

---

### Course Description

The Structural Stability Game Show!  
September 25, 2020

This webinar will feature a panel of engineers and academics, who will present their views on the root cause of three structural collapse case studies. The audience will then be given an opportunity to vote on which cause was most likely. Finally, the moderator will reveal and explain the true nature of the collapse.



Smarter.  
Stronger.  
SteelDay.

## AISC Live Webinars

---

### Learning Objectives

- Identify sources of instability for several structural configurations.
- Describe methods for how to approach stability analysis computationally and experimentally.
- Show how the structural factor of safety can be significantly impacted if one neglects considering stability.
- Explain the importance of communication during the design and construction of a project with case studies.



Smarter.  
Stronger.  
SteelDay.



## The Structural Stability Game Show!



Cliff D. Bishop  
*Exponent*



Patricia Clayton  
*UT Austin*



Larry Griffis  
*Walter P. Moore*



John D. Hooper  
*Magnusson Klemencic*



Ron Ziemian  
*Bucknell University*


SteelDay  
Everywhere

September 25, 2020  
[aisc.org/steelday](https://aisc.org/steelday)


### Case 1: Solar power support structure



## Background – Site and Structure



## Background – Site and Structure



## Background – Erection Process



11


## Background – The Failure



12



## Background – The Failure



13

## Contestants' discussion of root cause



14



## Contestants' discussion of root cause

A. Weld failure



15

## Contestants' discussion of root cause

A. Weld failure



B. Inadequate design



16



## Contestants' discussion of root cause

A. Weld failure



B. Inadequate design



C. Poor construction sequencing



17

## Contestants' discussion of root cause

A. Weld failure



B. Inadequate design



C. Poor construction sequencing



D. Extreme weather



18



## What was the root cause?

A. Weld failure



B. Inadequate design



C. Poor construction sequencing



D. Extreme weather



Time  
to  
Vote!



19

## What was the root cause?

A. Weld failure



B. Inadequate design



C. Poor construction sequencing



D. Extreme weather



Select  
your  
answer!



20



## What was the root cause?

A. Weld failure



B. Inadequate design



C. Poor construction sequencing




D. Extreme weather



21

## Sufficient weld


max. moment at welds  
between upper and lower  
weldment is  
**95 kip-in.**



22




## Sufficient weld



23



## Sufficient weld



24



## Adequate design



25

## Adequate design

Model	Top Bracing?	Total Load (kips)	
		Eigen	L-D
Case 1: Self-weight only	Unbraced	17.8	-
Case 2: Receiver + self-weight	Unbraced	6.1	5.6
Case 3: Receiver + self-weight	Fully Braced	30	-

weight of tower + receiver  
4.8 kips + 2.1 kips = 6.9 kips

26



## Adequate design




Figure 6.1 – Tower Buckling (G + Seismic X)

Figure 6.2 – Tower Buckling (G + Seismic Y)

27

Designer's CD's and calc's included:

- Analysis of *braced* structure for lifting
- Analysis of *unbraced* for wind only
- Explicit instructions for *inadequate* bracing



## Case 2: Dome scaffolding collapse



28



## Background



- Project required construction of 7 digester tanks
- Tanks were numbered from 17 to 23
- Dimensions
  - 125-ft diameter concrete tank
  - 50-ft tall
  - 1-ft thick wall and slab
- Base of tanks slopes down towards center
- Aluminum falsework used to support formwork and deck pour

29

## Background



### At the Time of the Accident:

- Tanks 17 and 18 had already been constructed; roof decks poured without incident
- Tank 19 was ready for concrete deck pour
- Tanks 20 and 21 had the falsework almost fully installed

30



## Background



### At the Time of the Accident:

- Concrete roof was being placed in Tank 19, moving south to north
- A little over half of the concrete had been placed

31

## The failure



32





## The Failure



- Falsework supporting the plywood in Tank 19 collapsed
- 29 persons on the roof deck
- 14 workers injured; 4 serious; **none** fatally injured
- Tanks 19, 20, and 21 were immediately put under Cal OSHA Order to Preserve, pending investigation

33

## Scaffold Layout



- Plywood formwork for concrete deck was supported on aluminum beams
- Layers of aluminum beams supported on aluminum shoring towers


34



## Scaffold Layout




- Top and bottom of the towers had screwjacks for adjustable extension
- Many of the towers also had 12-inch or 16-inch long sub-stringers at the top



35

## Scaffold Layout



36



## Observations – Tank 19



So... What caused the failure?

37

## Contestants' discussion of root cause



38



## Contestants' discussion of root cause

A. Stringer web buckling 



39

## Contestants' discussion of root cause

A. Stringer web buckling 

B. Screwjack extensions 




40



## Contestants' discussion of root cause

A. Stringer web buckling 

B. Screwjack extensions 

C. Inadequate bracing 





41

## Contestants' discussion of root cause

A. Stringer web buckling 

B. Screwjack extensions 

C. Inadequate bracing 

D. Too much concrete 



42



## What was the root cause?

A. Stringer web buckling



B. Screwjack extensions



C. Inadequate bracing



D. Too much concrete



Time  
to  
Vote!



43

## What was the root cause?

A. Stringer web buckling



B. Screwjack extensions



C. Inadequate bracing



D. Too much concrete



Select  
your  
answer!



44



## What was the root cause?

A. Stringer web buckling



B. Screwjack extensions



C. Inadequate bracing



D. Too much concrete



45

## Failure Modes and Contributors Considered

- Longer screwjacks
- Missing cross-braces
- Slip at base due to missing/failed wood shims at base
- Different joist layout
- No outer frame bracing
- Bracing not tied to the wall
- Weld failure in frame
- Failure of couplers between frames
- Sub-stringer buckling
- 12-inch sub-stringers
- Eccentric installation of sub-stringers
- Overloading of tower legs
- Uneven load distribution
- Unequal screwjack extensions
- Swivel vs. fixed screwjack ends



46



# Shoring System Design

**TABLE 4 - TOWER CAPACITIES WITH JACKS ONLY OR EQUIVALENT**

For 1 to 3 frame (up to 20' high towers, with 12" maximum screwjack extension top and bottom or with jacks extended 12" at one end and extension tubes at the other, extended not more than 16-1/2" using 5 and 6 foot high frames.

NOTE: For towers using only 4' high frames up to four frames high, loads in this table can be increased by 15%.

HEIGHT OF TOWER	SUPER HI-LITE FRAMES C/W INTERFRAME CROSSBRACES ALLOWABLE LOAD PER LEG	SUPER HI-LITE FRAMES WITHOUT INTERFRAME CROSS BRACING ALLOWABLE LOAD PER LEG
One tier	9,500 lb. (4320 kg.)	9,500 lb. (4320 kg.)
Two tiers	11,400 lb. (5190 kg.)	8,800 lb. (4000 kg.)
Three tiers	13,000 lb. (5943 kg.)	8,800 lb. (4000 kg.)

**TABLE 5 - TOWER CAPACITIES WITH JACKS AND EXTENSION TUBES AS INDICATED**

For 2 and 3 frame high towers using 4' and 6' high frames completely interbraced with extension tubes and jacks therein at one end extended 12" and with jacks extended 12" or extension tubes extended 16-1/2" in the other end replacing the jacks. (See maximum extension options.)

NOTE: One tier of 5' high frames can also be used in a tower and still interbraced if used as the bottom frame.

If towers are not completely interbraced, reduce all capacities by 25%. For towers using only one frame high with extension tubes and jacks as indicated below reduce all load capacities by 15% (as one frame cannot be interbraced). For towers using only 4' high frames, 2, 3, and 4 frame high completely interbraced capacities can be increased by 15%.

LENGTH EXTENSION TUBES EXTENDED COMPLETE WITH JACKS IN TUBES	MAX. EXTENSION	SAFE WORKING LOAD FOR EACH LEG USING PLUS JACKS EXTENDED	SAFE WORKING LOAD FOR EACH LEG USING EXTENDED 12"
EXTENDED 12" AT ONE END AND JACKS ONLY ON EXTENSION TUBES EXTENDED 16-1/2" AT THE OTHER END	30"	10,500 lb. (4760kg.)	10,500 lb. (4760kg.)
A. EXT. TUBES 8"x24" of 2-jacks =	32"	9,500 lb. (4300kg.)	9,500 lb. (4300kg.)
EXTENSIONS 16"x24" of 2-jacks =	38"	7,500 lb. (3400kg.)	7,500 lb. (3400kg.)
AT ONE END 20"x24" of 2-jacks =	44"	8,500 lb. (3860kg.)	8,500 lb. (3860kg.)
ONLY 20"x24" of 2-jacks =	50"	8,000 lb. (3630kg.)	8,000 lb. (3630kg.)
30"x24" of 2-jacks =	56"	7,500 lb. (3400kg.)	7,500 lb. (3400kg.)

The following "B" Section is for towers with extension tubes and jacks at both ends of a tower or if no jacks are used at one end, the extension tubes can be extended 14" more replacing the jacks, providing they are long enough.

B. EXT. TUBES 8"x24" of 2-jacks =	40"	9,500 lb. (4320kg.)	10,000 lb. (4535kg.)
EXTENSIONS 16"x24" of 2-jacks =	48"	7,000 lb. (3170kg.)	7,500 lb. (3400kg.)
AT BOTH 20"x20"x24" of 2-jacks =	64"	5,000 lb. (2270kg.)	5,700 lb. (2585kg.)
ENDS 20"x20"x24" of 2-jacks =	76"	4,500 lb. (2040kg.)	4,500 lb. (2040kg.)

Not recommendable without auxiliary bracing.

NOTE: 30" EXTENSION TUBES MUST NOT BE EXTENDED MORE THAN 20-1/2".  
48" EXTENSION TUBES MUST NOT BE EXTENDED MORE THAN 32-1/2".

**SAFETY FACTOR = 2.5 BASED ON ULTIMATE TEST RESULTS**

- Maximum applied load per leg = 9,000 lb
- Allowable load per leg = 8,800 lb
- From Table 4 in Appendix G
  - 3 tier tower
  - Maximum 12-inch screwjack extension
- Factor of safety = 2.5
- Minimum ultimate capacity per leg = 22,000 lb

47

# Shoring System Design



**ALLOWABLE LOAD PER LEG**

All values for load for Shoring Towers with continuous screw jacks (or top of 12" both top and bottom of tower as maximum of both bottom of column to top of base and bottom of tower to top of 12") is indicated below.

1 Frame High	8,100
2 Frames High	7,000
3 Frames High	7,000

Consult PC9508 for further details.

**ICON AND GENERAL NOTES, SPECIFICATIONS AND TYPICAL DETAILS FOR SUPER HI-LITE HEAVY DUTY ALUMINUM SHORING SYSTEM**

Patent Construction Systems  
RECOMMENDATIONS AND ERECTION NO. SS-660


100-109-091

- Design drawings specified
  - up to 9 tier towers with no outer frame bracing
  - 16-inch long sub-stringers on top of tower legs
- The effect of the sub-stringers on load capacity of the towers was not calculated.

48




## Design Loads (200 psf)



Design load included a 40 psf live load in addition to concrete and equipment weight




## Actual Loads (160 psf)



Actual loads still considerably higher than original design load of 9,000 lbs



## Full-Scale Field Testing



- Conducted full-scale field testing of exemplar shoring
- Towers were incrementally loaded to failure
- Failure due to sub-stringer web buckling leading to global buckling of scaffold towers
- The peak applied loads on legs with sub-stringers were
  - 14,850 lbs (Tower 1)
  - 13,750 lbs (Tower 2)
- Failure loads significantly below design ultimate of 22,000 lbs


51



52



## Finite-Element Analysis




A finite element model of shoring tower was prepared in ABAQUS

The model was used to study the effect of various factors on the strength and stability of the shoring towers

53

## Finite-Element Analysis




### Factors investigated using F-E model

- Longer screwjacks
- No outer frame bracing
- Sub-stringer buckling
- Uneven load distribution
- Missing cross-brace
- Unequal screwjack extensions
- Missing/failed wood shims at base
- Weld failure in frame
- Failure of frame couplers

54



## Finite-Element Analysis



**Sub-stringers are the primary contributor to reduction in scaffold capacity**

55

## Case 3: Building roof collapse



56



# Background



57

# The Failure



58




# The Failure



59


# Design



60



### As-Built



61

### The Failure



62



## Contestants' discussion of root cause



63

## Contestants' discussion of root cause

A. Freak storm (overload)



64



## Contestants' discussion of root cause

A. Freak storm (overload)



B. Missing support (improper construction)



65

## Contestants' discussion of root cause

A. Freak storm (overload)



B. Missing support (improper construction)



C. Local member effects



66



## Contestants' discussion of root cause

A. Freak storm (overload)



B. Missing support (improper construction)



C. Local member effects



D. Improper design



67

## What was the root cause?

A. Freak storm (overload)



B. Missing support (improper construction)



C. Local member effects



D. Improper design



**Time**  
**to**  
**Vote!**



68



## What was the root cause?

A. Freak storm (overload)



B. Missing support (improper construction)



C. Local member effects



D. Improper design



**Select  
your  
answer!**



69

## What was the root cause?

A. Freak storm (overload)



B. Missing support (improper construction)



C. Local member effects




D. Improper design



70




## Failure Mechanism – web crippling



71

## Failure Mechanism – web crippling



Ignore open section for calculations  
 – upper bound estimate

Description	P (kip)
Allowable Load (ASD)	1.9
Exponent Calculated Capacity	3.5
Non-Factored Loads (service loads)	4.0
BOCA Requirements <sup>1</sup>	6.4
“Expert” Report	7.4 (??)

*Building Officials and Code Administrators requires assemblies to withstand 2.5 times live load for testing*

72



# Opposing Expert report

\_\_\_\_\_, Ph.D., P.E.  
\_\_\_\_\_, P.L.L.C.  
Professional Engineering Services

June 8, 2006

RE: Supplemental report, Broadway Business Park

Dear Mr. Commissioner:

This report covers the ongoing investigation of the Broadway Business Park, Oklahoma City, Oklahoma. Big 20, which is consistent with my prior reports on collapsed framing wall stresses and moments as discussed occurred principally at the steel stud wall assemblies that were removed. Subsequent damage was caused to the masonry support the masonry structure.

The roofs were supported by open web, bar joists that were in turn supported by bearing assemblies built into the steel stud framing walls. Three of these bearing assemblies were removed from the buildings and tested for capacity. The test results indicate that the bearing assemblies as constructed were sufficient to support the design loads that were required at the time of construction of the building. The tests indicate that the capacity of the bearing assemblies was at least 7,429 lbs, which is in my opinion sufficient to support design loads consistent with the governing building code.

The roofs were supported by open web, bar joists that were in turn supported by bearing assemblies built into the steel stud framing walls. Three of these bearing assemblies were removed from the buildings and tested for capacity. The test results indicate that the bearing assemblies as constructed were sufficient to support the design loads that were required at the time of construction of the building. The tests indicate that the capacity of the bearing assemblies was at least 7,429 lbs, which is in my opinion sufficient to support design loads consistent with the governing building code.

**Removal of the Bearing Assemblies**  
In May of 2006, we excavated the wall stud bearing assemblies from three sites within the two buildings at Broadway Business Park. The assemblies are labeled as follows, which are consistent with my original report dated October 4, 2004:

- X S 13 from Building 200
- X N 24 from Building 240
- X N 13 from Building 240

Photographs were taken to document the condition of the wall studs and the bearing assemblies prior to their removal from the buildings. The bearing assembly from N 26, Big 20 is pictured in Fig. 1 in the photograph, we can view water damage to the exterior sheathing that is consistent with the photographs taken in July of 2004.

The bearing assemblies for testing were chosen in that these were assemblies with relatively minor damage compared to most of the bearing assemblies in the two buildings. Even so, all of the bearing assemblies that were chosen and removed exhibited varying degrees of damage prior to testing.

The roofs were supported by open web, bar joists that were in turn supported by bearing assemblies built into the steel stud framing walls. Three of these bearing assemblies were removed from the buildings and tested for capacity. The test results indicate that the bearing assemblies as constructed were sufficient to support the design loads that were required at the time of construction of the building. The tests indicate that the capacity of the bearing assemblies was at least 7,429 lbs, which is in my opinion sufficient to support design loads consistent with the governing building code.

BP 2461

73

# Opposing Expert Report


Table 1. Results of Capacity Tests on Bearing Assemblies

Design Criteria				Test Results		
Design Dead Load (DL) (psf)	Design Live Load (LL) (psf)	Total Design Load (DL + LL) (psf)	Boca 1981 Test Load (psf)	Bearing Assembly	Test Load (lbs)	Equivalent Total Load per Square Foot (psf)
12	20.8	32.8	52	N 13	7429	61
12	20.8	32.8	52	N 24	5167 ??	42
12	20.8	32.8	52	S 13	3942 ?	32




74





### What is the design strength?



“For since the fabric of the universe is most perfect, and is the work of a most wise Creator, nothing whatsoever takes place in the universe in which some relation of maximum and minimum does not appear.”

Leonhard Euler in *Lineas Curvas (Elastic Curves)*, 1744

Thank you for your participation!



## The Structural Stability Game Show!



Cliff D. Bishop  
Exponent



Patricia Clayton  
UT Austin



Larry Griffis  
Walter P. Moore



John D. Hooper  
Magnusson Klemencic



Ron Ziemian  
Bucknell University

SteelDay  
Everywhere

September 25, 2020  
[aisc.org/steelday](http://aisc.org/steelday)



**AISC** | Questions?



## PDH Certificates

---

- You will receive an email on how to report attendance from: [registration@aisc.org](mailto:registration@aisc.org).
- Be on the lookout: Check your spam filter! Check your junk folder!
- Completely fill out online form. Don't forget to check the boxes next to each attendee's name!



## PDH Certificates

---

- Reporting site (URL will be provided in the forthcoming email).
- Username: Same as AISC website username.
- Password: Same as AISC website password.



Smarter.  
Stronger.  
SteelDay.



**AISC** | Thank you



Smarter.  
Stronger.  
SteelDay.

