

AISC Live Webinars

Thank you for joining our live webinar today.
We will begin shortly. Please standby.

Thank you.

Need Help?

Call ReadyTalk Support: 800.843.9166

The Use of NDT in the Rehabilitation of Major Steel Bridges: Two Case Studies

October 22, 2018



**Smarter.
Stronger.
Steel.**

AISC Live Webinars

Today's live webinar will begin shortly. Please stand by.

As a reminder, all lines have been muted. Please type any questions or comments through the chat feature on the left portion of your screen.

Today's audio will be broadcast through the internet.
Alternatively, to hear the audio through the phone, dial:

(888)-378-4398
Passcode: 240120



**Smarter.
Stronger.
Steel.**



AISC Live Webinars

Audio Options

Today's audio will be broadcast through the internet.

Alternatively, to hear the audio through the phone, dial:

(888)-378-4398
Passcode: 240120



**Smarter.
Stronger.
Steel.**

AISC Live Webinars

AIA Credit

AISC is a Registered Provider with The American Institute of Architects Continuing Education Systems (AIA/CES). Credit(s) earned on completion of this program will be reported to AIA/CES for AIA members. Certificates of Completion for both AIA members and non-AIA members are available upon request.

This program is registered with AIA/CES for continuing professional education. As such, it does not include content that may be deemed or construed to be an approval or endorsement by the AIA of any material of construction or any method or manner of handling, using, distributing, or dealing in any material or product.

Questions related to specific materials, methods, and services will be addressed at the conclusion of this presentation.



**Smarter.
Stronger.
Steel.**



AISC Live Webinars

Copyright Materials

This presentation is protected by US and International Copyright laws. Reproduction, distribution, display and use of the presentation without written permission of AISC is prohibited.

© The American Institute of Steel Construction 2018

The information presented herein is based on recognized engineering principles and is for general information only. While it is believed to be accurate, this information should not be applied to any specific application without competent professional examination and verification by a licensed professional engineer. Anyone making use of this information assumes all liability arising from such use.



**Smarter.
Stronger.
Steel.**

AISC Live Webinars

Course Description

The Use of NDT in the Rehabilitation of Major Steel Bridges: Two Case Studies
October 22, 2018

This webinar focuses on the rehabilitation of two major steel bridges, the Sherman Minton Bridge in Louisville and the Delaware River Bridge in Bristol, PA, each of which were rehabilitated and repaired using a combination of nondestructive testing, materials sampling and testing, engineering analysis, and emergency construction contracts. The two case studies show how major steel bridges can be quickly assessed and returned to service using a combination of tools.



**Smarter.
Stronger.
Steel.**



AISC Live Webinars

Learning Objectives

- List various non-destructive testing options for rehabilitation of existing steel structures.
- Describe the process of qualifying a unique ultrasonic testing procedure.
- Explain the communication techniques that can facilitate coordination between designers and the inspection team, when assessing the rehabilitation of an existing structure.
- Name steps that can be taken to perform a full forensic assessment of a steel structure.



**Smarter.
Stronger.
Steel.**

The Use of NDT in the Rehabilitation of Major Steel Bridges: Two Case Studies



Frank Russo, PhD, PE
Technical Director, Bridge Engineering
Michael Baker International
Philadelphia, PA



**Smarter.
Stronger.
Steel.**



Two Case Studies....with very different outcomes

Sherman Minton Bridge




PA NJ Turnpike Delaware River Bridge



Sherman Minton Bridge over the Ohio River at Louisville



Sherman Minton Bridge – Structure Details



- Structure Information
 - Tied Arch
 - 2 – 800 foot spans
 - Double-deck structure
 - Navigable waterway underneath

11

Bridge History

Prior inspections revealed visual cracks in isolated welds

Prior NDT inspections documented multiple internal weld defects

No comprehensive assessment of the bridge condition was ever conducted

Large amount of unknowns

12

Type of Material

- "T-1" Steel
 - VERY high strength steel
 - Limited ductility
 - Susceptible to FRACTURE at cold temperatures and with small cracks


Sensitive Details

- Tie girder welds
- Diaphragm plates
- Lateral bracing details

Contributing Factors

Tie Girder Welds


- T-1 Steel (known issues with welding)
- Tie girder butt-welded thin to thick plates to allow for drilling of tie girder splices, i.e. to maintain the section capacity



14


Tie Girder Welds

176 Individual welds per tie x 2 ties x 2 spans = 704 potential fracture sites



15


Diaphragm Lugs



16

Diaphragm Lugs

33 diaphragms per tie x 2 ties x 2 spans x 8 lugs per diaphragm x 2 legs = 2112 welds



17


Lateral Bracing Plates



18

Lateral Bracing Plates

11 panels x 2 plates per panel x 2 ties x 2 spans = 88 connection plates



19

Enhanced Bridge Inspection

20

Inspection & Testing

- COMPLETE hands-on visual inspection of EVERY INCH of weld metal on the tie girder
 - What can we find?
- Nondestructive testing (UT, MT, RT, X-Ray)
 - What can we find that we can't even see?
- Extensive sampling of bridge materials – over 100 cores taken
 - How strong, how tough, how big of a crack is “too big”?
- The MOST comprehensive visual, NDT & physical testing program ever conducted on this bridge



21

Non-Destructive Testing (NDT)

Performance testing of NDT technicians



22

Initial Repairs

23

Initial Repairs – Lugs & Lateral Bracing Plates

- Retrofit diaphragm lugs and lateral bracing connection plates
 - Why?
 - Nearly impossible to inspect thoroughly
 - Each could serve as a fracture initiation site



24





Diaphragms – Before & After

25

Diaphragms – Bolted Retrofit



26



Lateral Bracing Plates - Existing



Lateral Bracing Plates – Bolted Retrofit



Tie Girder Welds


- It's what we CAN'T see that's the problem....



29

Tie Girder Welds – Repairs

- Use of selected coring repairs




30

Engineering Approach

31

Why Even Small Cracks Can Matter





32




Fitness for Service Evaluation

• **BS 7910:2005** --- *GUIDE TO METHODS FOR ASSESSING THE ACCEPTABILITY OF FLAWS IN METALLIC STRUCTURES*

- Hypothesize combinations of temperature, load and flaws
- Determine if the bridge can be kept open



Material Assessment



35

Fitness for Service Conclusions

Some initial concern about allowing the bridge to remain in service at temperatures around 30F.

Bridge closed Friday September 9th 2011 @ 4 PM after a crack that should not have been stable at ambient temperatures was found.

Next steps...now what to do ????

36




Emergency Bridge Closure

During removal of the 3rd lateral bracing plate, a critical flaw was discovered.

Problem detected Thursday evening – bridge ordered closed Friday afternoon

37


Why we closed the bridge ...



38

Dog-Bone Retrofit

- Isolate potential crack propagation




Retrofit Design Considerations



Discovery & Solution Timeline


Inspection NTP to Intermediate Repair	• 3.5 months
Intermediate Repair to Finding which closed the bridge	• 3 weeks
Bridge Closure to Complete NDT work	• 3 weeks
Bridge Closure to Advertisement of Contract Documents	• 3 weeks

45



46








49



50




Copyright © 2018
American Institute of Steel Construction



Sherman Minton Conclusions

- Detailed inspection including NDT is sometimes warranted, especially for bridges where cracking problems have been noted
- NDT plus material sampling are key elements to a Fitness for Service Analysis
- Sometimes a major retrofit is unavoidable. This is not always the case, i.e. Fremont Bridge in Oregon

51



Day 1: January 20


Fracture discovered by painting contractor

Immediate Action

- Remove Traffic on and below bridge.
- Clearing the Unit of Contractor Material
- Stabilize Truss




Location of Fracture



- 3 Span Continuous Unit: Piers 10 – 13. Total Length \approx 647'
- 4 Span Continuous Unit: Piers 13 – 17. Total Length \approx 1078'


Temperature History

- Fracture occurred prior to January 20th
- Neighbors heard loud noise on or about December 16th, 2016
- “Shook the ground”
- 35 days before fracture discovered



55

Fracture and Evidence of “Plug Welds”



56

Fractured Chord After Removal

- W 14x314 Man-Ten Steel
- $t_f = 2.28''$
 $t_w = 1.41''$



57


Fracture Cause

- Mis-drilled holes during fabrication
- Attempt to fill holes with weld metal
- 1" diameter, 2.3" deep hole
- Hole not completely filled
- Slag, cracks in weld metal, lack of fusion, etc.
- HAZ around edge of hole
- Brittle fracture initiated at hole edge, propagated through member
- No fatigue crack growth seen

58



Sample Orientation

- Photos of samples overlain on the fractured U20-U19' chord




59

Lehigh's Investigation



60



UT Testing Approach

Phase I	Phase II	Phase III
Phase I <ul style="list-style-type: none">• Development of UT testing protocols• Preparation of test plates• Onboarding of technicians• Qualification testing	Phase II <ul style="list-style-type: none">• Expansion of connection testing• Additional qualification testing	Phase III <ul style="list-style-type: none">• Selective full length member testing

61

Phase I UT NDT Testing

- Development of UT approach and objectives
- *“To establish a uniform Ultrasonic Testing approach for the discovery of major weld defects remaining in plug welded hole repairs, made during the bridge construction. Potential areas for defective weld sites being investigated, are in the flanges of W shaped rolled members.”*

62





Ultrasonic Testing Program

- Needed a method that could find weld-filled holes
- Straight wave scan from flange edges
 - Down from top edge
 - Up from bottom edge



UT Testing Procedure Schematic




65

All Inspectors Performance Tested



Development of UT Testing Approach

- Develop limits of testing
- Test “dashed” members on North truss, PA side only as first screening (i.e. about 1/8th of tension members)



67

Phase II NDT UT Testing


Expand the testing 8-fold to include all tension and reversal members on the PA and NJ deck truss approach spans

Continue pattern of testing end 3-ft. regions adjacent to main gusset plate connections

On-board many new inspectors from numerous firms


- Continue process of technician testing
- Develop orientation graphics to enhance project communication
- Require mandatory end-of-day reporting and consistent report format preparation

68




3-Span NDT UT scope

- 88 total members tested at 2 ends
 - 22 members per truss line, 2 trusses, 2 states



4-Span NDT UT scope

- 156 total members tested at 2 ends (up from 14 members at 2 ends)
 - 41 members per truss, 2 trusses, 2 states




71

Phase III NDT UT Testing

- Expand the testing to a fraction of members for the full length
- Members met several criteria
 - Tension members only
 - Defined as “failure critical” in a prior study of the bridge by another consultant
- Chose 21 members in each state for testing

72

UT Indications at U7-U9 PA 3-Span



- Several indications in one area
- One class A – rejectable
 - Criteria doesn't make much sense, it was developed for welds
- Cores taken of 2 worst indications
- Sectioned, RT'd, MT'd

75

Removed Cores - Sectioned

- Two cores shipped to Purdue




- Sectioned. No plug welds found



76

Radiographic Testing at High Steel

- Clean RT test result – inside flange





- Original orientation



77

Radiographic and MT Testing



- Small indications noted by MT testing
- No idea if that is what UT detected

78

UT Indications @ L6-L8 PA 4-Span


- Possible filled holes found
- Gage line indicates possible filled holes



79

Remedial Actions

- Removed paint. Holes are filled...with something
- Core two locations to verify no welding at these filled holes
- Confirmed left-most hole is a mistake. Right holes (2 and 3) are mis-drilled then shifted shop fasteners.



80



Filled Hole Investigation

A close-up photograph of a hole in a steel girder. The hole is filled with a dark material. The surrounding steel is dark and shows some surface texture. A bolt head is visible to the left of the hole.

81






Filled Hole Investigation

A close-up photograph of two holes in a steel girder. Both holes are filled with a dark material. The surrounding steel is dark. A bolt head is visible to the right of the lower hole.

82







Summary of UT

- 277 members tested. 3 ft. limits each end
- Zero weld-filled-holes were found
- Some odd mechanically filled holes
- One location (U7-U9) with strong UT indications cored. No welding and virtually no internal discontinuities
- Removed chord scanned prior to delivery to Lehigh. No other plugs present

86

Material Testing / Forensics

87

Material Testing Program

- Portions of fracture surface cut out of member and shipped to Lehigh
- Lehigh investigation included:
 - Chemical and mechanical tests
 - Optical microscopy
 - SEM
 - Etc.
- Comprehensive material testing program
- Intended to characterize material throughout the deck truss side spans
 - Gussets
 - Jumbo members
 - Man-Ten
 - Carbon Steel
 - Etc.

88




Material Testing Program

- Purpose was to characterize the material used in the bridge
- Was the fractured member substantially different than the material in the rest of the bridge?
- Compare with historical information on similar material
- Compare Heavy shapes to others
- Compare Man-Ten to carbon steel.


89

PA Testing Plan



90

NJ Testing Plan



91

Material Testing


240 Charpy V-notch samples – fracture toughness

10 Tension samples – yield and ultimate strengths

4 compact tension samples – fracture toughness directly


Chemical analysis

Samples shipped to laboratory for machining of specimens



92


Sampling from Cores



93

Core Sampling Detail

- Various Specimens from Thick Cores



94

Material Callout on Shop Drawings

“Do no tack welding or welding on
Manten – A242”

Do no tack welding or welding on Manten - A242
steel except where welding is detailed. Use
Class E7018 electrodes when welding is detailed.

WORKMANSHIP NOTES

Rivets - 1" dia. Unless Noted
Holes - 1-1/16" dia. Unless Noted
Material - "CC" - Copper Bearing Carbon Steel - BILLING SUBDIV. [A]
"MT" - Manten Steel - BILLING SUBDIV. [B]
Rivets 1" dia. - Copper Bearing Manganese Steel [B]
Rivets 7/8" and 3/4" dia. - Copper Bearing Carbon Steel [A]
Reaming - Subpunch or subdrill 13/16" dia. and ream to size as
per Drawing P1.
Edge - "FC" - Flame Cut
Preparation - "FCS" - Flame Cut and Flame Soften. All flame cut
edges of Manten Steel shall be flame softened.
See Drawing P1 for complete material and workmanship specifications.
thick & over

rd
flanges to in flanges

162 APPENDIX
USS DESIGN MANUAL FOR HIGH STRENGTH STEELS 1962

USS MAN-TEN STEEL

A high-strength manganese-copper steel intended primarily for weight reduction by means of greater strength in applications involving moderate forming. It is considered a weldable grade provided mild steel electrodes are used and good welding technique and workmanship are maintained. It is not considered suitable for spot welding.

MECHANICAL PROPERTIES	THICKNESS RANGES		
	1/2 in. and Under in Thickness	Over 1/2 to 1 1/2 in. incl.	Over 1 1/2 to 3 in. incl.
Yield Point, min, psi.....	50,000	45,000	40,000
Tensile Strength, min, psi.....	75,000	70,000	65,000
Elong. in 2 in., min, per cent.....	20	—	22
Elong. in 8 in., min, per cent.....	18	19	19
0.180 in. and heavier.....	18	19	19
Cold Bend.....	180°D=1t	180°D=2t	180°D=3t

The minimum yield point and tensile strength requirements will be reduced by 5,000 psi when annealing or normalizing is specified, or when furnished in coils.

ASTM Standard Specimens, minimum number of tests and ductility modifications apply.

CHEMICAL COMPOSITION (For information purposes only)	C	Mn	P	S	Si	Cu
	Composition Range, per cent.....	.25 max	1.10/1.60	.045 max	.05 max	.30 max
Typical Composition, per cent.....	.22	1.40	.020	.036	.07	.27

164 APPENDIX
USS DESIGN MANUAL FOR HIGH STRENGTH STEELS 1962

USS MAN-TEN (A242) STEEL

FOR RIVETED AND BOLTED BRIDGES, BUILDINGS AND TOWERS

A high-strength steel intended primarily for use in structural members of riveted and bolted bridges, buildings, and towers. The characteristics of USS MAN-TEN (A242) Steel make it particularly applicable for structures of riveted construction requiring high strength with atmospheric corrosion resistance equal to that of copper steel.

MECHANICAL PROPERTIES	THICKNESS RANGES		
	3/4 in. and under	Over 3/4 to 1 1/2 in. incl.	Over 1 1/2 to 4 in. incl.
Yield Point, min, psi.....	50,000	46,000	42,000
Tensile Strength, min, psi.....	72,000	70,000	65,000
Elong. in 8 in., min, per cent.....	18	19	19
Elong. in 2 in., min, per cent.....	—	—	24


180° Cold Bend.....
D=1t for thicknesses to 3/4 in. incl.
D=1 1/2t for thicknesses over 3/4 to 1 in. incl.
D=2t for thicknesses over 1 to 1 1/2 in. incl.
D=2 1/2t for thicknesses over 1 1/2 to 2 in. incl.
D=3t for thicknesses over 2 to 4 in. incl.

ASTM Standard Specimens, minimum number of tests and ductility modifications apply.

CHEMICAL COMPOSITION, PER CENT (For information purposes only)	C	Mn	P	S	Si	Cu
	ASTM A242 Ladle.....	.22 max	1.25 max	—	.05 max	—
Check.....	.26 max	1.30 max	—	.063 max	—	—
USS MAN-TEN A242 Ladle.....	.27 max*	1.10/1.60*	.04 max	.05 max	.30 max	.20/.35
Check.....	.31 max*	1.65 max*	—	.063 max*	—	—

*Deviations from ASTM A242





97


Mechanical Properties

Property	Test Results	ASTM A242 (1952 - Tentative)	USS Man-Ten (A242 Modified) (1954)	ASTM A440 (1959 - Tentative)
Yield Strength t ≤ 1.5 in.	43.8 min 45.1 avg 47.0 max	45.0 min	46.0 min	46.0 min
Ultimate Strength t ≤ 1.5 in.	83.0 min 85.9 avg 88.1 max	66.0 min	70.0 min	67.0 min
Yield Strength t > 1.5 in.	40.0 min 42.2 avg 44.0 max	40.0 min	42.0 min	42.0 min
Ultimate Strength t > 1.5 in.	77.1 min 80.0 avg 82.2 max	63.0 min	65.0 min	63.0 min

98




Initial Test Data (March 2017) – Compared to Historical Materials



99


Final ManTen CVN Results



100




Delaware River Bridge vs. Historical Data



101


Results

- Better classification of Man-Ten provided
- 1970's test data for A440 found
- Properties were consistent
- Lower fracture toughness than modern steels



102





Conclusions
Based on
Material
Testing

¼ thickness CVN tests for “non jumbo” shapes meet modern CVN requirements

¼ thickness CVN tests for “jumbo” shapes do not always meet the CVN requirements for FC and non-FC members

This steel was produced at a time when no such FC requirements existed

The steel is consistent with other A242 and A440 steels tested nearly twenty years later (1970’s research)

Steel was deemed as not unusual for the time of construction and not fundamentally flawed.

103



Conclusion ...
Why now?

Defect present since initial fabrication in 1954

No sign that anything changed in 63 years

Dead load increase about 17 years ago

Safespan added ~ 1 ksi to DL

Low temperature on assumed day of fracture

HAZ around edge of hole

Brittle fracture initiated at hole edge, propagated through member

No fatigue crack growth seen

104

Final Repair Photos

105




Vertical Jacking

106



Post-Tensioning and New Chord Segment



107



108



Final Splice



Additional Repairs



Load Testing of Repaired Structure



111

Delaware River Bridge Conclusions

NDT is a tool when “something goes wrong”

Useful for searching for other similar defects

Standard testing procedures and technician testing are essential

Helping owners understand what they should and shouldn't be looking for, or be able to expect to find, is important

112

Questions?



CEU / PDH Certificates

- You will receive an email on how to report attendance from: registration@aisc.org.
- Be on the lookout: Check your spam filter! Check your junk folder!
- Completely fill out online form. Don't forget to check the boxes next to each attendee's name!




CEU / PDH Certificates

- Reporting site (URL will be provided in the forthcoming email).
- Username: Same as AISC website username.
- Password: Same as AISC website password.



**Smarter.
Stronger.
Steel.**



Thank you.



**Smarter.
Stronger.
Steel.**

